

Estimate Only



503-657-5306
 503-481-2737
 PO Box 1452
 Clackamas, OR 97015
 www.fleetservicenorthwest.com

Attn: Equipment Manager
 Pending Estimate List
 3/19/2009

Customer

Pending Estimates Total **\$6,848.54**

Records show the items listed here have not been performed at this time 3/19/2009

This estimate is not a price quote. Labor rates are guaranteed for 45 days from estimate date. Labor hours shown are the estimated time a particular service will take, and do not include incidental or additional repairs or services that may become necessary. Services on this estimate may be based on visual inspections or preliminary diagnoses. Further diagnostics may reveal additional or alternative services or repairs are needed. Parts and material prices are beyond the control of Fleet Service Northwest and are subject to change at any time without notice. By agreeing to allow Fleet Service Northwest to perform the services listed on this estimate, you agree that Fleet Service Northwest may perform any incidental repairs or services that are deemed necessary by Fleet Service Northwest technicians during the performance of these services. You also agree to pay in full, before the vehicle is released from Fleet Service Northwest, the total amount of all invoices relating to the products and services on this estimate, as well as any other products and services that remain unpaid at that time.

<u>Service Description</u>	<u>Estimate Class</u>	<u>Estimated Cost</u>
Equipment Number		
E185 9/27/2008		
Replace Tires	Class Unknown	\$800.15
Replace all 4 tires. Goodyear 225/75R16E Wrangler HT.		
E309 2/18/2009		
Miscellaneous Repairs	Class 2 Leak	\$432.48
Diag. transmission fluid leak. Replace transmission extension housing.		
Equipment Number Total		\$1,232.63
Equipment Number		
E064 3/18/2008		
Miscellaneous Repairs	Class 3 Repair	\$85.09
Replace driver's side mirror glass.		
Ignition Tune-up	Class 3 Repair	\$499.38
Diag. misfires. Rplc distributor cap, rotor, spark plugs and wires.		
Fuel System Service	Class 2 Repair	\$133.18
Perform fuel system service, rplc fuel filter.		
Equipment Number Total		\$717.65
Equipment Number		
E208 10/1/2008		
Miscellaneous Repairs	Class Unknown	\$252.50
Diag. low power. Replace intercooler-to-intake manifold hose.		
Equipment Number Total		\$252.50

Estimate Only

Equipment Number

E291 1/27/2009

Miscellaneous Repairs	Class 3 Repair	\$652.31
Replace tie rods and tie rod ends. Perform 4 wheel alignment, adjust toe-in.		

E295 1/29/2009

Miscellaneous Repairs	Class 1 Leak	\$318.02
Diag. transmission fluid leak. Replace front driveshaft yoke, transmission output seal, front u-joint.		

Equipment Number Total	\$970.33
-------------------------------	-----------------

Equipment Number

E203 9/23/2008

Miscellaneous Repairs	Class Unknown	\$1,374.52
Diag. low power. Replace plugged catalytic converter and muffler. ADDITIONAL DIAGNOSTICS REQUIRED FOR CYL 5 MISFIRE.		

Equipment Number Total	\$1,374.52
-------------------------------	-------------------

Equipment Number

E308 2/18/2009

10w-30 Synthetic	Class Unknown	\$61.79
Changed oil and filter, lube chassis, checked lights and fluids. LABOR INCLUDES SERVICING AIR COMPRESSOR & HYDRAULIC FLUID & FILTER AS NECESSARY, AS WELL AS OVERALL INSPECTION.		

E315 2/27/2009

Replace Trailer Axle	Class Unknown	\$618.01
Diag. uneven tire wear. Replace trailer axle, inspect/adjust brakes, clean and repack wheel bearings, replace seals. 4-5 WEEK WAIT FOR CUSTOM FABRICATION OF AXLE		

Equipment Number Total	\$679.80
-------------------------------	-----------------

Equipment Number

E180 8/8/2008

Replace Tires	Class Unknown	\$206.36
Replace tire. 215/85R16E Wrangler HT.		

Equipment Number Total	\$206.36
-------------------------------	-----------------

Equipment Number

E062 2/15/2008

Miscellaneous Repairs	Class 3 Repair	\$605.58
Replace driver's door hinges, latch and strike pin.		

Miscellaneous Repairs	Class 2 Repair	\$350.46
Replace passenger exterior door handle, and rear cargo door handle. Replace passenger door hinge pins.		

Equipment Number Total	\$956.04
-------------------------------	-----------------

Equipment Number

E130 6/2/2008

Replace P/S Pump	Class 3 Repair	\$271.55
Diagnose inoperative power steering while stopped. Replace power steering pump.		

Miscellaneous Repairs	Class 2 Repair	\$187.16
Replace damaged oil filler cap. Replace headlight switch due missing headlight switch handle. HEADLIGHT SWITCH KNOB UNAVAILABLE INDIVIDUALLY		

Equipment Number Total	\$458.71
-------------------------------	-----------------

Customer Total	\$6,848.54
-----------------------	-------------------